#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

#### WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-019790 Address: 333 Burma Road **Date Inspected:** 13-Dec-2010

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** OBG

## **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Bao Qian.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA Inspector.

Component; OBG Anchor Plate Assembly

PCMK: AP3031-001 Weld No: 417 Welder: 200113

Weld Repair No. WR18953 WPS-345-SMAW-3G(3F)-Repair

Component; OBG Anchor Plate Assembly

PCMK: AP3031-001



#### WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Weld No: 437 Welder: 216086

Weld Repair No. WR18957 WPS-345-SMAW-3G(3F)-Repair

Component; OBG Anchor Plate Assembly

PCMK: AP3031-001 Weld No: 315 Welder: 054013

Weld Repair No. WR18945 WPS-345-SMAW-3G(3F)-Repair

Bay 28

This QA Inspector observed the following work in progress for Bay 28.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Yang Bai Qiang.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS). Listed below are the locations that were identified by this QA Inspector.

Component; OBG Traffic Barriers

PCMK: E5-SB13067

Weld No: 026,031,057,062

Welder: 062265 WPS-B-P-2232-ESAB

Component; OBG Traffic Barriers

PCMK: E5-SB13062

Weld No: 001~012,032~043

Welder: 059466 WPS-B-P-2232-ESAB

## Blast Bay 1


This Caltrans QA Inspector and Mr. Bret Rice, and Mr. Mike Hasler performed a pre-blast visual inspection of the interior surface and internal components, Lift 4, SSDI tower subassembly, 116~131 meter mark to the bottom surface of the double diaphragm. Surface defects and base metal surface irregularities that required grinding were marked up with colored chalk, and weld defects that require welding were taped with gray masking tape for repair after the coating has been applied. ZPMC QC and ABF inspection personnel were present during the inspection and informed of QA findings.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

# WELDING INSPECTION REPORT

(Continued Page 3 of 3)





# **Summary of Conversations:**

No significant conversations

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Leavitt,Kelly	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer